

All Saints Church, Mackworth
Record Photographs 17th and 19th May 2021



View into south porch



Debris clearance underway within the chancel



Debris clearance to zone E4



View of chancel & sanctuary zones F3 and G3 cleared



Note depth of debris within vestry



Commencement of south aisle restraint scaffold 1



Commencement of south aisle restraint scaffold 2



View of nave from chancel



Temporary propping to vestry wall 1



Temporary propping to vestry wall 2